



2012 Abu Dhabi Grand Prix

From	The FIA Stewards of the Meeting	Document	41
To	The Team Manager Red Bull Racing	Date	03 November 2012
		Time	22:30

The Stewards received a report from the Race Director that car 1 failed to return to the pits under its own power as required under Article 6.6.2 of the FIA Formula One Technical Regulations.

The Stewards heard from the driver and team representatives and studied telemetry evidence that showed the reason why the car was stopped.

The Stewards accepted the explanation and considered the incident as being a case of force majeure.

However a report was received from the Technical Delegate that showed during post-qualifying scrutineering an insufficient quantity of fuel for sampling purposes.

The Stewards determine that this is a breach of Article 6.6.2 of the FIA Formula One Technical Regulations and the Competitor is accordingly excluded from the results of the Qualifying Session.

The Competitor is however allowed to start the race from the back of the grid.

The FIA Stewards of the Meeting

Lars Osterlind

Radovan Novak

Derek Warwick

Khaled Bin Shaiban